

# Case Study 2



**genzyme**  
A SANOFI COMPANY

**END USER:**  
Genzyme Ltd

**LOCATION:**  
Haverhill, Suffolk

**PROJECT:**  
Site Improvements

**DOOR DETAILS:**  
7 No Bulldoors installed  
between December 2012  
& January 2013.



**IAC**  
International Automotive Components

**END USER:**  
IAC Group Ltd

**LOCATION:**  
Scunthorpe, North East  
Lincolnshire

**PROJECT:**  
Site Refurbishment

**DOOR DETAILS:**  
2 No Ramdoors & 5  
No Bulldoors installed  
between October 2012 &  
February 2013.



**END USER:**  
RPC Containers Ltd

**CONTRACTOR:**  
Barnfield Construction

**LOCATION:**  
Blackburn, Lancashire

**PROJECT:**  
New Warehouse

**DOOR DETAILS:**  
2 No Ramdoors & 4  
No Bulldoors installed  
between September &  
November 2012



**END USER:**  
Jeld-Wen UK Ltd

**LOCATION:**  
Penrith, Cumbria

**PROJECT:**  
Site Improvements

**DOOR DETAILS:**  
4 No Bulldoors installed  
between August &  
September 2012